



www.mbdcentral.com
 (Click on "Sample" to see sample PDF)

Product	Description	Notes	3D Screengrab	2D Drawings	PMI Notes	Step203	Point Cloud Check sum	XL Worksheet for AS9102F3	
3DXMD	3D eXtracted Manufacturing Document	Contains all data needed to manufacture and inspect a part or assembly	X	X	X	X	X		Sample
Quotation	3D Quotation Document	Contains enough data for quotation purposes.	X		X				Sample
RDD	Reference Dimensioned Document	Contains thickness dimensions for in process inspection (Cutcom Adjust)		X					Sample
MDD	Masking Dimensioned Document	Contains dimension drawing of masking areas.		X					Sample
ADD	Assembly Dimensioned Document	Contains dimensioned drawing of all assembly components.	X	X	X				Sample
FPD	Flat Pattern Document	Contains full size flat pattern drawing (with X factors) and STEP203 file..		X		X			Sample
V4XMD	V4 eXtracted Manufacturing Document	Contains all data needed to manufacture and inspect a part or assembly	X	X	Customer Attached Parts List	X	X		Sample
AFID	Annotated Features Inspection Document	Contains point data in datum system for FAI bench inspection (no CMM!)	X	X		X		X	Sample
PCID	Point Cloud Inspection Document	Contains point data in datum system for FAI bench inspection (no CMM!)	X	X		X		X	Sample